

vvaler Quality Farameter wormoning Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: C</th></have<>	County: Clackamas Agency: C	
077	7.83		13		14	minimums been met for this day?	ENTRY POINT	
31	7,99		1.3		4		A	
	*					PWS ID 4100547 MULINO WATER DISTRICT		
						Sample	period: 02,/3035 Month/Year	
						Number of	excursions during this month:	
						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
						Refe	Minimum Water Quality Parameter(s) as set by State:	
				-				
(No = 1)	V = Exc	cursion	n) Tota	l N's		Print Nam Signature Date: 02	: mur progen	
	Send to DWP within 10 days after end of sampling period							

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp