

vvaler Quality Parameter Monitoning Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: C</th></have<>	County: Clackamas Agency: C	
09.	7.82		13		M	minimums been met for this day?	ENTRY POINT	
23	785		13		4		В	
	*						PWS ID 4100547	
						MULINO WATER DISTRICT		
						Sample	period: 12/2024 Month/Year	
						7		
Number of excursions				excursions during this month:				
						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
						Refe	erence	
							Minimum Water Quality Parameter(s) as set by State:	
							pH 7.3	
					-			
						Drint Non	20: 2/20 11 100 5 21	
						Signature	ne: MANUN TROSPON	
(No = 1	V = Exc	cursion	n) Tota	l N's	0	Date: /a	The point	

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp