

vvaler Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: C</th></have<>	County: Clackamas Agency: C	
96	780		1,3		4	minimums been met for	ENTRY POINT	
90	784		13		4	this day?	В	
	*					L.	PWS ID 4100547	
						and the second s	MULINO WATER DISTRICT	
						Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
-								
						Reference		
							Minimum Water Quality	
						Parameter(s) as set by State:		
							pH 7.3	
-								
						Print Nan	ne: MARVIN TRAGION	
						Signature	: Marin Truster	
(No = 1	V = Ex	cursion	n) Tota	I N's		-	nin 10 days after end of sampling period	

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp