

Entry Point Monitoring Form



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	10.51				Y
2	10.96	47.88			Y
3	8.27				Y
4	8.01				Y
5	7.98				Y
6	8.06				Y
7	8.05				Y
8	8.04				Y
9	8.03				Y
10	8.01				Y
11	7.98				Y
12	7.98				Y
13	7.96				Y
14	7.96	41.04			Y
15	7.93				Y
16	7.91				Y
17	7.93				Y
18	7.93				Y
19	7.98				Y
20	7.98				Y
21	8.00	47.88			Y
22	8.00				Y
23	8.01				Y
24	8.01				Y
25	8.01				Y
26	8.01				Y
27	8.01				Y
28	8.06	41.04			Y
29	8.05				Y
30	8.06				Y
31	8.06				Y

<<Have
minimums
been met for
this day?

County: Tillamook Agency: REGION 1

ENTRY POINT

EP-A

PWS ID 4100556

NETARTS WATER DISTRICT

Sample period: July 2025
Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.4
Alk 40.0 (Alkalinity)

Print Name: DAVID Hancock
Signature: [Signature]
Date & Phone#: 8/1/25 971-241-7203

Send to DWP within 10 days after end of
sampling period

(No = N = Excursion) Total N's 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>