Entry Point Monitoring Form



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	8,06				
2	8.05				
3	8.08				
4	8.0				
5	3,0	54,72			
6	7.96				
7	7.95				
8	7,96				
9	7,96				
10	7.93				
11	7.93	57.88			
12	7.84				
13	7.84				
14	7,89				
15	7.89				
16	7,91				
17	8.03				
18	8.30				
19	8,03	41.04			
20	7.93				
21	8.03				
22	7.95			4	
23	795				
24	7.88				
25	7.96	47,83			
26	7.95				
27	7.91				
28	7.91				
29	7.93				
30	7.95				
31					
No - 1	N = Fy	cursion) Tota	I NI'e	A

< <have< th=""><th>County: Tillamook Agency: REGION 1</th><th></th></have<>	County: Tillamook Agency: REGION 1							
minimums	ENTRY POINT							
been met for this day?	EP-A							
PWS ID 4100556 NETARTS WATER DISTRICT Sample period: ARGUST 2025								
							Month/Year	

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

pH 7.4 Alk 40.0 (Alkalinity)

	DAVID Hancock	
Signature: _	Our Hanne	
Date & Phon	e#: 503.842-9405	-9/3/2025
	within 10 days after end of	7 - [

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/