DHS

oregon department of human services

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Sili	Y/N		iums been		ENTRY POINT								
1	7.21				Y	met fo	or this day?	PWS ID: 41	0	0	5	5	7	1			
2	7.26				Y						•	•		-			
3	7.19				Y		Syste	em Name:	City of Newberg								
4	7.23				Y												
5	7.23				Y		Entr	ry Point:	Entry Point A								
6	7.15				Y												
7	7.14				Y		Samp	le Period:	May-2025								
8	7.11				Y			Month / Year									
9	7.33				Y												
10	7.24				Y												
11	7.14				Y		Number of excursions* during this month: 0										
12	7.12				Y		(Count the number of days when any WQP was less than the minimum required)										
13	7.23				Y		required)										
14	7.15				Y												
15	7.23				Y												
16	7.22				Y	Total excursions during the previous 5 months:											
17	7.26				Y		(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)										
18	7.25				Y		CACUISIONS										
19	7.26				Y			For DHS use on	lv.							-	
20	7.20				Y				.,								
21	7.19				Y			Minimum Water Quality Parameters as set by									
22	7.02				Y			State:									
23	7.28				Y			рН		7.00							
24	7.27				Y			Alk				(Alka	alinity)				
25	7.23				Y			PO4				(Orth	hopho	sphat	te)		
26	7.19				Y			Sili				(Silic	cate)				
27	7.17				Y												
28	7.17				Y												
29	7.17				Y	4		Print Name:				Jor	Hodg				
30	7.13				Y	4		Signature: Jon HodgkmVs									
31	7.07				Y	4		Date:				6	6/2/202	25			
(No = N = Excursion) Total N's 0																	
						1	Se	end to DHS within	n 10 d	ays a	fter er	nd of s	ampli	ng pe	eriod		

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

05-2025- PWS 41 00557 L&C CC

Phone: 971-673-0405