

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Da	у рН	Alk	Phos	Other	Y/N	< <have< th=""></have<>
1						minimums ENTRY POINT
2	8,0				Y	been met for this day? PWS ID: 41 0 0 5 6 2
3						System Name: Chehalem M+ Sunridge Warn
5						Entry Point: 3/630: 3/555 NF (- 1.17)
6						Entry Point: 3/630; 3/555 NE Canter Land Sherwood, Sherwood, Canter Land Sherwood, Cante
7						Month/Year
8	7.8				Y	Number of excursions* during this month:
9						(Count the number of days when any WQP was
10						less than the minimum required)
11						
12						Total excursions during the previous 5 months:
13	7 0					(Over 9 excursions in 6 months is a violation. Entry
14	7.9				Y	Point and Distribution excursions are cumulative)
6						For OHA use only
17						
18						Minimum Water Quality
19						Parameters as set by
20	8.1				y	pH 7.2
21						Alk (Alkalinity)
22		96.5				PO4 (Orthophosphate)
23						Other ()
24						
25						
26						
27	8.1			,		Print Name: Suzanne M. Boyd
28						Signature: Juane m. Bond
29						Date: 8/27/2023
30						Send to DWP within 10 days after end of
31						sampling period
= N	= Excu	rsion)	Total	N's		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/