

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
"/	7,3				1	minimums been met for this day?	ENTRY POINT	
7	7,0				9		EP-A	
14	7.2				y			
19	7.0	*			Y	PWS ID 4100564 BAY HILLS WATER ASSOCIATION		
25	7.0				Y			
						Sample period: APR 21  Month/Year		
				i i			, *	
						Number of excursions during this month:		
					1	parameter(s) fall below the minimum set by the State.		
		***************************************				Refe	rence	
							Minimum Water Quality Parameter(s) as set by State:	
							pH 7.0	
, , , , , , , , , , , , , , , , , , ,								
ì								
					100			
						Print Name: John MacKown  Signature: John MacKown  Date: 1 M 4 21		
o = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period								

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp