

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
3	4.0				Y	minimums	ENTRY POINT	
8	7,0				4	been met for this day?	EP-A	
13	7,0				4	tilis day :		
27	7,0	3.			4	and the solution of	PWS ID 4100564	
28	9.6				7	В	AY HILLS WATER ASSOCIATION	
29	7,3				17	leading localizations.		
- ,						Samp	le period: July 1 2021  Month/Year	
							Month/Year	
-						0		
				- 1	<u> </u>	Number	of excursions during this month:	
				§ (§ )		(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).		
							sion' is any day in which the water quality	
						The same of the sa	r(s) fall below the minimum set by the	
					•	State.		
						j		
						Re	eference	
-				-		ou. Man complete a present	Minimum Water Quality	
							Minimum Water Quality Parameter(s) as set by State:	
							· arameter(e) as set by states	
						The state of the s	pH 7.0	
							and the second s	
						- 25		
1				9				
						Duint Names Tahn MacKayan		
			Print Name: John MacKown					
						Signature: John Makon		
						Date: _	VI Aug ZI	
(No = N	No = N = Excursion) Total N's Send to DWP within 10 days after end of							
				,	5 8	sampling	g period	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp