

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI		
6	7.0				4	minimums	ENTRY POINT		
11	7.1				Y	been met for this day?	EP-A		
18	7.1				Y		PWS ID 4100564		
27	7,0	-			Y				
	,					BAY	HILLS WATER ASSOCIATION		
						_	DaT/21		
						Sample period: OcT/2/ Month/Year			
							MOHUI/Teal		
				10 supp.	7				
				1		(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).			
						An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
					1 4				
						Refe	rence		
						The second			
							Minimum Water Quality Parameter(s) as set by State:		
					-		raiameter(s) as set by State.		
							pH 7.0		
						TOTAL AMERICAN PROGRAM			
						in the state of th			
					380	Anni garanta antara da ant			
						Print Name: John MacKown			
					-	Signature: Out Mer Kom			
						Date: /	Short I		
$N_0 = N$	l = Excı	I Irsion)	Total	N'e	0	1	NP within 10 days after end of		
			1000	143	0	sampling p			

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp