

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Other	Y/N	<-Have ENTRY POINT
1						
2						been met for this day? <b>PWS ID: 41</b> 0 0 5 6 4
3	7.3	40			Y	
4						System Name: <u>Bay Hills Water Association</u>
5						Entry Point: <u>Treatment Plant</u>
6						Sample Period: <u>11/23</u>
7						Month/Year
8						Number of excursions* during this month: <u>0</u>
9						(Count the number of days when any WQP was
10	7.3	40			Y	less than the minimum required)
11						
12						Total excursions during the previous 5 months: 0
13						(Over 9 excursions in 6 months is a violation. Entry
14						Point and Distribution excursions are cumulative )
15						For OHA use only
16						
17						Minimum Water Quality
18	7.2	35			Y	Parameters as set by
19						pH 7.0
20						Alk <sup>30</sup> (Alkalinity)
21						PO4 n/a (Orthophosphate)
22						Other $n/a$ (Other phase)
23						
24	7.3	35	<b> </b>		Y	
25	1.3	33			I	
26 27						
27						Print Name: <u>John MacKown</u>
28 29						Signature:
29 30						Date: <u>12-1-23</u>
30					$\vdash$	Send to DWP within 10 days after end of
		 /	 m) <b>⊤</b>		0	sampling period
(No = N = Excursion) <b>Total N's</b> $0$						

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/