

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Othe r	Y/N	<-Have ENTRY POINT
1	7.1	30			у	been met for
2						this day? PWS ID: 41 0 0 5 6 4
3						System Name: <u>Bay Hills Water Association</u>
4						Entry Point: Treatment Plant
5						Sample Period: 1/24
6						Month/Year
7						Number of excursions* during this month: 0
8						(Count the number of days when any WQP was
9	7.3	35			Y	less than the minimum required)
10						
11						Total excursions during the previous 5 months: 0
12						(Over 9 excursions in 6 months is a violation. Entry
13						Point and Distribution excursions are cumulative)
14						
15						For OHA use only
16	7.1	35			Y	
17						Minimum Water Quality
18						Parameters as set by
19						pH 7.0
20						Alk 30 (Alkalinity)
21		• •				PO4 n/a (Orthophosphate)
22	7.1	30			Y	Other n/a ()
23						
24						
25						
26						
27						Print Name: <u>John MacKown</u>
28						Signature:
29						Date: <u>2/2/24</u>
30	71	75			V	Send to DWP within 10 days after end of
31	7.1	35 Sursion) Tota	IN'S	Y 0	sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/