

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН		Phos	Other	Y/ N
1	PD				
2	PD				
3	7.0	32			Y
4	PD				
5	PD				
6	PD				
7	PD				
8	PD				
9	PD				
10	PD				
11	7.3	32			Y
12	PD				
13	PD				
14	PD				
15	PD				
16	PD				
17	PD				
18	PD				
19	PD				
20	7.3	32			Y
21	PD				
22	PD				
23	PD				
24	PD				
25	PD				
26	PD				
27	PD				
28	PD				
29	7.3	32			Y
30	PD				
31	PD				
Tota	l N's				0

(No = N = Excursion)

< <have minimums<="" th=""><th colspan="4">ENTRY POINT</th></have>	ENTRY POINT					
been met for this day?	PWS ID: 41	0 0 5 6 4				
System Name: <u>Bay Hills Water Association</u> Entry Point: Treatment Plant						
Sample Period: 1/25						

Month/Year

Number of excursions* during this month: 0 (Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: 0
(Over 9 excursions in 6 months is a violation. Entry
Point and Distribution excursions are cumulative)

For OHA use only Minimum Water Quality Parameters as set by						
рН	7.0					
Alk	30	(Alkalinity)				
PO4	n/a	(Orthophosphate)				
Other	n/a	()				

Print Name: John MacKown					
Signature:					
Date 2/1/25					
Send to DWP within 10 days after end of					
sampling period					
PD=PlantDown					