

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/ N
1	7.1	35			Y
2	PD				
3	PD				
4	PD				
5	PD				
6	PD				
7	7.0	35			Y
8	PD				
9	7.2	40			Y
10	PD				
11	PD				
12	PD				
13	PD				
14	PD				
15	PD				
16	7.3	36			Y
17	PD				
18	PD				
19	PD				
20	PD				
21	7.2	36			Y
22	PD				
23	PD				
24	7.3	40			Y
25	PD				
26	7.3	40			Y
27	PD				
28	PD				
29	7.4	40			Y
30	PD				
31	PD				
Tota	l N's				0

(No = N = Excursion)

< <have minimums<="" th=""><th colspan="4">ENTRY POINT</th></have>	ENTRY POINT					
been met for this day?	PWS ID: 41	0 0 5 6 4				
System Name: <u>Bay Hills Water Association</u> Entry Point: Treatment Plant						
Sample Period: 9/25						

Month/Year

Number of excursions* during this month: 0 (Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: 0 (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only Minimum Water Quality Parameters as set by						
рН	7.0					
Alk	30	(Alkalinity)				
PO4	n/a	(Orthophosphate)				
Other	n/a	()				

Print Name: <u>John MacKown</u> Signature:				
Date 10/3/25				
Send to DWP within 10 days after end of				
sampling period				
PD=Plant Down				