

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	PO4	other	Y/N	<has sample<="" th=""></has>
1	77 SE YVD - 6/19/25	7.2	36			Y	met the minimums? DISTRIBUTION
2	77 SE YVD – 7/1/25	7.2	32			Y	PWS ID: 41- 00564
							System Name: Bay Hills Water
							Association
							Sample Period: June - July Month/Year
							Sample Frequency: 3 yrs
							Distribution Samples required: 1
							Number of excursions during this Sample Period = <u>0</u>
							(Number of locations when any WQP was less than the minimum.)
							Note: Entry Point and Distribution Excursions are cumulative. Add Entry
							Point and Distribution Excursions to get total for sample period.
							For OHA use only
							Minimum Water Quality Parameters as set by
							pH 7.0
							Alk (Alkalinity)
							PO4 (Orthophosphate)
							Other
						0	Duint Name at 1st 14
(N = No = Excursion) Total N's						Print Name: John MacKown	
						Signature:	
							Date: <u>7/1/25</u>

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/