

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
6	24				Y	minimums	ENTRY POINT	
13	7.1				Y	been met for this day?	EP-A	
20	7-2	AND THE STREET STREET STREET			Y		PWS ID 4100564	
26	71			***************************************	17			
	,					BAY HILLS WATER ASSOCIATION		
							Tag 21	
						Sample period: FEB & Month/Year		
							Month/Year	
						Number of excursions during this month:		
						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).		
						An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
					**			
						Reference		
							3.100	
							Minimum Water Quality	
				and a second		d-HECKER AND	Parameter(s) as set by State:	
							pH 7.0	
, ,								
						Print Name: John MacKown Signature: Of Mackown		
						Date: //	MAR2/	
No = N	V = Excu	ırsion)	Tota	N's	0		NP within 10 days after end of	
						sampling p	eriod	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp