

Water Quality Parameter Monitoring Form  
Oregon Department of Human Services  
**Lead & Copper Rule Corrosion Control**

Day	PH	Y/N
1	7.9	Y
2	7.9	Y
3	7.9	Y
4	7.9	Y
5	7.9	Y
6	7.9	Y
7	7.9	Y
8	7.9	Y
9	7.9	Y
10	7.9	Y
11	7.9	Y
12	7.8	Y
13	7.8	Y
14	7.8	Y
15	7.8	Y
16	7.8	Y
17	7.8	Y
18	7.8	Y
19	7.8	Y
20	7.8	Y
21	7.8	Y
22	7.8	Y
23	7.8	Y
24	7.8	Y
25	7.7	Y
26	7.7	Y
27	7.7	Y
28	7.7	Y
29	7.7	Y
30	7.7	Y
31	7.7	Y
<b>Total N's</b> (No = N = Excursion)		<b>0</b>

<<Have minimums been met for this day?	
County: Lincoln	Agency: REGION 2
<b>ENTRY POINT</b>	
EP- A (WTP)	
<b>PWS ID 4100566</b>	
City of Newport	
Sample period: Mar-21	

**Number of excursions during this month:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).  
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

<b>Minimum Water Quality Parameter(s) as set by State:</b>	
pH	<b>7.0</b>

Print Name: Steve Stewart

Signature: 

Date: 4/1/2021

Sent to DWP within 10 days after end of sampling period.