

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.1	30			Y
2					
3					
4					
5					
6					
7					
8	7.2	30			У
9					
10					
11					
12					
13					
14					
15	7. 2	30			У
16					
17					
18					
19					
20					
21					
22	7.1	30			У
23					
24					
25					
26					
27					
28					
29	7.1	30			У
30					
31					
					0

<have inimums</have 	ENTRY POINT				
een met for is day?	PWS ID: 41	0 0 5 7 3			
System Name: SAND-N-WOOD MOBILE					
VILLA					
<b>Entry Poin</b>	t: PUMP HO	DUSE			
Sample Pe	riod: Mac	sch 2025			
		Month/Year			

Number of excursions\* during this month: O (Count the number of days when any WQP was less than the minimum required)

For OHA use only					
Minimum Water Quality Parameters as set by					
рН	F				
Alk	F	(Alkalinity)			
PO4		(Orthophosphate)			
Other					

Print Name: TERESA ROMERO
Signature: Junious
Date: 4/10/2025
Send to DWP within 10 days after end of

Send to DWP within 10 days after end of sampling period

(No = N = Excursion) Total N's

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/