

(No = N = Excursion) Total N's

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""></have<>
1	7.1	30			Y	minimums ENTRY POINT
2						been met for this day?  PWS ID: 41  0 0 5 7 3
3						uns day:
4						System Name: SAND-N-WOOD MOBILE
5						VILLA
6						Entry Point: PUMP HOUSE
7						Sample Period: 6/1/25 - 6/30/25
8	7.4	30			У	Month/Year
9						Number of excursions* during this month:
11						(Count the number of days when any WQP was
12						less than the minimum required)
13						Total excursions during the previous 5 months:
14						(Over 9 excursions in 6 months is a violation. Entry
15	7.2	30			V	Point and Distribution excursions are cumulative)
16	7 &				/	
17						For OHA use only
18						Minimum Water Quality
19						Minimum Water Quality Parameters as set by
20						
21						pH (Aller linites)
22	7.3	30	ļ		Y	Alk (Alkalinity)
23						PO4 (Orthophosphate)
24			۰			Other(
25	<u> </u>					
26						
27				<u> </u>		
28 29						Print Name: TERESA ROMERO
30						Signature: Anum au
31						Date: 7/10/2025
	L	1		L		Send to DWP within 10 days after end of
_					0	sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/