

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4	7.6	30			Y
5				*	
6					
7					
8					
9	7.60	31	,		Y
10					
11					-
12					
13					
14					
15				, , , , , , , , , , , , , , , , , , , ,	
16	8.0	30			7
17				·	
18					
19					
20					
21					
22					
23	7.7	29			7
24					
25					
26					
27					
28					
29,					
30	7.7	28.1			Ч
31					•
10 = N	1 = Exc	cursion) Tota	N's	d

<pre><<have been="" day?<="" for="" met="" minimums="" pre="" this=""></have></pre>					
r					

County: Clackamas Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100580

NORTH CLACKAMAS COUNTY WC

Sample period: 4/23

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference							
Minimum Water Quality Parameter(s) as set by State:							
pH Alk	7.5 25.0	(Alkalinity)					

Send to DWP within 10 days after end of sampling period