

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2 3 4 5					
4					
5					
6					
7	7.7	34.3			Y
8					'
9					
10					
11					
12					
13					
14	7.6	34.4			Y
15					,
16					
17					
18					
19					
20					
21	7.6	33.4			Y
22					
23					
24					
25					
26	7				
27					
28	7.6	32.4			Y
29					1
30					
31					
No = N = Excursion) Total N's					Ø

<<Have minimums been met for this day?

County: Clackamas Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100580

NORTH CLACKAMAS COUNTY WC

Sample period: 10/2024

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality
Parameter(s) as set by State:

pH 7.5
Alk 25.0 (Alkalinity)

Print Name: Bret Bienerth
Signature: With Dienrich

Date & Phone#: 5 Nov. 201 971-356

Send to DWP within 10 days after end of sampling period