

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рΗ	AIK	Phos	Other	Y/I
1					
2		·			
3					
4					
5	•				
6					
7	7.96	35.8			Y
8					ι
9					
10					
11					
12					
13	7.83	35.4			Y
14					1
15					
16					
17					
18					
19					
20					
21	7.97	37.7			1
22					
23					
24					
25					
26					
27	7.92	37.1			Y
28					,
29					
30					
31					
lo = N	l = Exc	cursion)Total	l N's	Ø

< <have< th=""></have<>
minimums
been met for this day?
this day?
i

County: Clackamas Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100580

NORTH CLACKAMAS COUNTY WC

Sample period: 8/2025

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality) as set by State:
pH Alk	7.5 25.0] (Alkalinity)

Print Name:	Steve	Presti	wood
Signature:	th	Owh	1
Date & Phon	e#: 9-4	-25	771-295-1052

Send to DWP within 10 days after end of sampling period