

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.57				Υ
2	7.38				Υ
3	7.42				Υ
4	7.56				Υ
5	7.49				Υ
6	7.49				Υ
7	7.53	27.36			Υ
8	7.63				Υ
9	7.62				Υ
10	7.46				Υ
11	7.64				Υ
12	7.66				Υ
13	7.47				Υ
14	7.34	27.36			Υ
15	7.57				Υ
16	7.71				Υ
17	7.61				Υ
18	7.73				Υ
19	7.67	`			Υ
20	7.66				Υ
21	7.50	27.36			Υ
22	7.75				Υ
23	7.60				Υ
24	7.56				Υ
25	7.52				Υ
26	7.58				Υ
27	7.47				Υ
28	7.48	27.36			Υ
29	7.51				Υ
30	7.31				Υ
31	7.69				Υ
lo = N = Excursion) <b>Total N's</b>					0

<<Have
minimums
been met for
this day?</pre>

County: Tillamook Agency: REGION 1

## **ENTRY POINT**

EP-A

## PWS ID 4100585

**OCEANSIDE WATER DISTRICT** 

Sample period: July/2025

Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference					
Minimum Water Quality Parameter(s) as set by State:					
pH Alk	7.3 25.0	(Alkalinity)			

Print Name: Christian Anderson

Signature:

Date & Phone#:

(503)842-6462

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/