

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Da; 1 2 3 4 5	у рН	AHK	Phos	Other	Y/N
1					
2	_			······································	
3	_				
4	_				
5					
6	8.2	1			Y
7	,				, ₁
8	_				
9	_				
10					
11					_
12					-
13 14		·			
14					-
15					_
16					
17					_
18	-,				
19		,			
20 21 22 23 24	8.21				Y
21	8.21				Y
22	8.24				4
23				[_	
					-
25					
26	_				
27	8.26				Y
28					_
29					
30	-				
	-				
K	Las Pacos	.waiaw\		X 11 _ [_/ I

< <have< th=""><th>County: Multromah Agency: REGION 1</th></have<>	County: Multromah Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-C
And the second of the second o	PWS ID 4100668
	ROCKWOOD PUD
Sample pe	riod: JAH. / 2021 Month/Year

Number of excursions during this month: _______

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

,
Minimum Water Quality Parameter(s) as set by State:
pH 7.8
Print Name: JAY BREEN
Signature:
Date & Phone#: 2 / 1/2021 503 1674-4517
Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period

Reference -