

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

<b>B</b>	7-11	N.ILC	m	Other	V/AI		T	
Day	/ pH	AHK	Phos	One	1/10	< <have< td=""><td>County: Multnomah Agency: REGION 1</td></have<>	County: Multnomah Agency: REGION 1	
1		·				minimums	ENTRY POINT	
2						been met for	EP-C	
3						this day?		
4							' PWS ID 4100668	
5						ROCKWOOD PUD		
6					क्षेत्र हैं			
7	,				-	Sample period: MARCH / 2021  Month/Year		
8				-				
9	1							
10	prof.			***************************************		Number of excursions during this month: _ダ_		
11	8.38			· · ·	Y	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
12	/ .							
13								
14								
15	8.43				Y	State.		
16								
17						⊢Reference —		
18	//,							
19		,				Minimum Water Quality Parameter(s) as set by State:		
20								
21	100					pH 7.8		
22	1000							
23								
24								
25								
26						<b>₽</b>		
27						Print Name: JAY BREEN  Signature:		
28								
	8.31				Ý			
	8.33				Y			
7					+	Send to L sampling	OWP within 10 days after end of	
 N = N	= Excı	rsion)	Total	N's T	Ø	samping	репоч .	
	,	,	, GLERI	., .,	$\varphi$			

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/