

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day 1	рН	Alk	Phos	Other	VIN
1	7.6	45			VÌ
2	7.6	244			VI
3 & 5	7.7	48			<u>y</u> Ì
4	7.5	46	Ì		<b>Y</b> Ì
	7.5	45			Y
6	ブら	45			Y
7	7.6	54	1		Y
8	7.7	.50			Y
9 10	7.6	46	}		Y
10	7.6	49			Y
11 12	7.6	-51		{	y I
12	7.6	45	1	[	<u>y</u>
13 14	Z.Z.	46	-	į	У
14	7.7	45			<u>y</u>
15	7.6	50	1		Y
16	7.6	48			X
17	. <u>7.8</u>	50			Y
18	7.7	.50	<u> </u>		Y
19	7.6	51	ļ		Y
20	7.6	47		<u> </u>	Y
21	7.6	49	<u> </u>		X
22	7.7	55	-		X
23	Contraction of the local division of the loc	53		} {······	Y
24	7.6	.56	<u> </u>	<u> </u>	X.
25	7.6	418	<u> </u>	<u> </u>	Y
26	7.6	51	-		<u>y</u>
27	7.6	49		<u> </u>	<u>                                     </u>
28	7.6	49		1	<u>                                     </u>
29	1.6	50			<u>  Y</u>
30-	1/.6	415		<u> </u>	Y
31	<u> </u>	1	1	<u> </u>	
No =	N = Ex	cursio	n) Tota	n N's	0

< <have< th=""><th>County: Coos Agency: REGION 2</th><th></th></have<>	County: Coos Agency: REGION 2				
minimums	ENTRY POINT				
been met for this day?	EP-A				
	<sup>1</sup> PWS IID 4100672				
	powers, city of				
Sample p	orico: June /2021				

Number of excursions during this month: \_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fail below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk 34.0 (Alkalinity)
Print Name:
Signature:

Data & Phone#:

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/