

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

,	Day	<b>у рН</b>	Alk	Phos	Other	NIN			
	1	7.6	63				<<-lave	County: Coos Agency: REGION 2	
	2	7.5	161			Ϋ́	minimums been met for this day?	ENTRY POINT	
	3	7.5	60		<u> </u>	1		EP-A	
	Q.	7.5	64		<u> </u>	7		PWS ID 4100672	
	5	7.7	69			7	POWERS, CITY OF		
	6	7.6	63	į		Υ			
	7	7.7	62			У	Sample period: August 2024 Month/Year  Number of excursions during this month: 0  (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.  Reference  Minimum Water Quality		
	8	7.7	63		į	Y			
	9	7.6	65			у			
	10 17	17.6	65			7			
	have made and	7.7	168			Y			
	12	7.5	68			Υ.			
	13	7.6	67			Y			
	14	7.5	68			١٧,			
	15	7.6	68		,	У			
	16	7.6	65			Y			
	17	7.6	65			·y			
	18	7.6	65			Υ			
	79	7.5	62			Y			
	20	7.6	61			Y	Parameter(s) as set by State:  pH 7.2  Alk 34.0 (Alkalinity)		
	21	7.8	65	-		У			
	22	7.6	61			Y			
	23	7.5	62			Y			
	24	7.5	63.			y			
	25	7,5	65			Y			
	26	.7.6	70			y			
	27	7.5	66			У			
	28	7.6	66	_		У	Print Name: Signature: Date & Phone#:		
	29	7.6	60			У			
	30.	7.5.	55			У			
L	31	7.5	56			<b>Y</b>	Send to	DWP within 10 days after end of	
(N	No = N = Excursion) Total N's						sampling	period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/