

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.4	60			Y
2	7.4	56			Y
3	7.4	57			Y
4	7.5	60			Y
5	7.5	60			Y
6	7.5	64			Y
7	7.5	62			Y
8	7.5	61			Y
9	7.4	62			Y
10	7.4	60			Y
11	7.4	58			Y
12	7.5	60			Y
13	7.5	64			Y
14	7.5	68			Y
15	7.5	64			Y
16	7.5	66			Y
17	7.6	70			Y
18	7.5	70			Y
19	7.5	70			Y
20	7.6	70			Y
21	7.6	72			Y
22	7.7	74			Y
23	7.6	71			Y
24	7.6	74			Y
25	7.7	75			Y
26	7.8	70			Y
27	7.8	76			Y
28	7.9	75			Y
29	7.8	75			Y
30	7.9	73			Y
31					

(No = N = Excursion) Total N's 0

<<Have
minimums
been met for
this day?

County: Coos

Agency: REGION 2

ENTRY POINT

EP-A

PWS ID 4100672

POWERS, CITY OF

Sample period: September 2025
Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation.
Entry Point and Distribution excursions are
cumulative). An 'excursion' is any day in which the
water quality parameter(s) fall below the minimum
set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.2

Alk 34.0 (Alkalinity)

Digitally signed by David Terrusa
Reason: I Have reviewed this document and submit it for
the record.
Location: PO Box 226; Langlois, OR. 97450
Date: 2025.10.05 19:56:48 -07'00'

Print Name: _____

Signature: _____

Date & Phone#: _____

Send to DWP within 10 days after end of
sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>