



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.4				Y
2	7.4				Y
3	7.3				Y
4	7.4				Y
5	7.4				Y
6	7.4				Y
7	7.4				Y
8	7.4				Y
9	7.5				Y
10	7.5				Y
11	7.3				Y
12	7.4				Y
13	7.3				Y
14	7.4				Y
15	7.4				Y
16	7.5				Y
17	7.4				Y
18	7.5				Y
19	7.9				Y
20	7.8				Y
21	7.5				Y
22	7.6				Y
23	7.5				Y
24	7.5				Y
25	7.4				Y
26	7.4				Y
27	7.4				Y
28	7.7				Y
29	7.3				Y
30	7.5				Y
31	7.6				Y

<<Have minimums been met for this day?

County: Douglas Agency: S

ENTRY POINT

A.

PWS ID 4100699

REEDSPORT, CITY OF

Sample period: Oct 2021
Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality Parameter(s) as set by State:

pH 7.2

Print Name: Jeff Blum

Signature: Jeff Blum

Date: 11-4-21

= N = Excursion) Total N's 0

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp