

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Other	Y/N	<< Have	County: Tillamook Agency: REGION 1
1	OFF				Υ	minimums	ENTRY POINT
2	OFF				Υ	been met for	
3	OFF				Υ	this day?	В
4	OFF				Υ		PWS ID 4100708
5	OFF				Υ	Rockaway Beach Water Dist.	
6	OFF				Υ		
7	OFF				Υ	Sample F	Period: Apr-25
8	OFF				Υ		Month/Year
9	OFF				Υ	Number of excursions during this month:	
10	OFF				Υ		
11	OFF				Υ		
12	OFF				Υ		
13	OFF				Υ	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative), An 'excursion' is anyday in which water quality parameter(s) fall below the minimum set by the State.	
14	OFF				Y		
15	OFF				Υ		
16	OFF				Y		
17	OFF				Υ		
18	OFF				Υ		
19	OFF				Y		
20	OFF				Y	Reference	
21	OFF				Υ		
22	OFF				Υ	l N	Ainimum Water Quality
23	OFF				Υ	Par	ameter(s) as set by State:
24	OFF				Υ		
25	OFF				Υ	pH 7.2	
26	OFF				Υ		
27	OFF				Υ		
28	OFF				Υ	Print Name: Luke Shepard Signature:	
29	OFF				Υ		
30	OFF				Υ		Date: 1-May-25

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 732-4381 Website: wwww.ohd.hr.state.or.us/dwp