

# Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N	<< Have minimums been met for this day?	
1	OFF				Y		<div style="text-align: right; font-size: small;">County: Tillamook Agency: REGION 1</div> <h3 style="text-align: center;">ENTRY POINT</h3> <h2 style="text-align: center;">B</h2> <h3 style="text-align: center;">PWS ID 4100708</h3> <p style="text-align: center;">Rockaway Beach Water Dist.</p> <hr/> <p><b>Sample Period:</b> <u>Mar-26</u></p> <p style="text-align: right; font-size: small;">Month/Year</p> <p><b>Number of excursions during this month:</b> <u>0</u></p> <p>(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative), An 'excursion' is anyday in which water quality parameter(s) fall below the minimum set by the State.</p> <div style="border: 1px solid black; padding: 10px; margin: 10px 0;"> <p style="text-align: center; font-size: small;">Reference</p> <p style="text-align: center;"><b>Minimum Water Quality Parameter(s) as set by State:</b></p> <p style="text-align: center; font-size: large;">pH <span style="border: 1px solid black; padding: 2px 10px;">7.2</span></p> </div> <p><b>Print Name:</b> Luke Shepard</p> <p><b>Signature:</b> </p> <p><b>Date:</b> <u>1-Apr-26</u></p>
2	OFF				Y		
3	OFF				Y		
4	OFF				Y		
5	OFF				Y		
6	OFF				Y		
7	OFF				Y		
8	OFF				Y		
9	OFF				Y		
10	OFF				Y		
11	OFF				Y		
12	OFF				Y		
13	OFF				Y		
14	OFF				Y		
15	OFF				Y		
16	OFF				Y		
17	OFF				Y		
18	OFF				Y		
19	OFF				Y		
20	OFF				Y		
21	OFF				Y		
22	OFF				Y		
23	OFF				Y		
24	OFF				Y		
25	OFF				Y		
26	OFF				Y		
27	OFF				Y		
28	OFF				Y		
29	OFF				Y		
30	OFF				Y		
31	OFF				Y		

(No = N = Excursions) **Total N's** 0

Send to DWP within 10 days after end of sampling period  
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone: (503) 732-4381 Website: www.ohd.hr.state.or.us/dwp