

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	8.)				4
2	7.6	Bris outland i son	BAN BALLING V NAVARAN TO BERT AND AND A	William to 1818 is	1
3	79				7
4	78				Y
5	7.7				Y
6	8.0				У
7	8.1				Y
8	8.0				Y
9	8.1				4
10	8.1				4
10 11 12 13	811				У
12	8.1				V
13	8,0				Y
14 15	8:1				Y
15	8,0	en e			y
16					
17					
18	7.8				1
19	7.8				4
20	7.8			2.	
21	7.8				1
22	1				<u>'</u>
23	15				
24	7.5	lock!			У
25					
26	-				
27	7.5				V
28					
29	7.5				4
30					
31					

< <have minimums<="" th=""><th>County: Columbia Agency: REGION 1 ENTRY POINT</th></have>	County: Columbia Agency: REGION 1 ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100792
	SCAPPOOSE, CITY OF
Sample p	eriod: <u>OCTOBER 2021</u>
- Guillpio p	Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).

An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk (Alkalinity)
Print Name: Darry Sykes
Signature: Samil Syles
Date & Phone#: 11/9/2621 503-369-0297
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

-Reference