

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.4				4
2	7.5				4
3					8
4	7.3				Y
5					
6					
7					
8	7.4				4
9					
10	7.5				7
11	7.8				4
12	7.8				4
13	7.8				4
14	7.9				4
15	7.7				Y
16	7.7				4
17	7.3				Y
18	7.3				15
19	74				4
20	7.7				14
21	7.7				14
22	7.8				17
23	7,6				17
24	7.6	_			T
25	7.7				14
26	7.6				4
27	7.7				4
28	7.7				17
29	7.4				Y
30	7.4				T
31					
No =	N = Ex	cursic	n) Tot	al N's	0

< <have< th=""><th>County: Columbia Agency: REGION 1</th></have<>	County: Columbia Agency: REGION 1					
minimums	ENTRY POINT					
been met for this day?	EP-A					
	PWS ID 4100792					
	SCAPPOOSE, CITY OF					
Sample period: November 2021						
	Month/Year					

Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality

parameter(s) fall below the minimum set by the State.

Reference	
Minimum Water Quality Parameter(s) as set by State:	
pH 7.2 Alk (Alkalinity)	
Print Name: Darry Sykes Signature: Darry Sykes Date & Phone#: 12/2/202/503-369-07	97

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Deference