

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.5				Y
1 2 3	7.3				Y
3	7.3				Y
4	7.3				4
5	7.3 7.3 7.5				Y
6	7.5				4
7	7.6				4
8	7.6				Y
9	7.6 7.6 7.6 7.7 7.7 7.5 7.5 7.4 7.5				1
10	7.5				4
11	7.7				Y
12 13 14	7.5				Ч
13	7.5	J. W. W.			4
14	7.4				7
15	7.5				4
16	7.3	1			7
17	7.3				Y
18 <del>-</del> 19	14.4				ý
19	7.4				Y
20	7.4				Y
21	7.6				1
22	7.6				1
23	7.4				Y
_	7.5				Y
25	7.5				Y
26	7.4				Y
27	7.4				4
28	7.3				4
29	7.5				7
30	73				7
31	7.3				4
(No =	No = N = Excursion) <b>Total N's</b>				

< <have< td=""><td>County: Columbia Agency: REGION 1</td></have<>	County: Columbia Agency: REGION 1			
minimums	ENTRY POINT			
been met for this day?	EP-A			
	PWS ID 4100792			
	SCAPPOOSE, CITY OF			
Sample p	eriod: October 2023			
	Month/Year			

An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk (Alkalinity)
Print Name: Darry Sykes
Signature: Dany Dyles
Date & Phone#: 1/3 2023 503-369-0297
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Reference