

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.6				У
3	7.6				Y
3					
4					
5	7.4				Y
6	7.6				Y
7					<u> </u>
8	7.7	7			Y
9	7.7				4
10					
11					
12	7.7				7
13	7.7				Y
14	7.6		-		Y
15	7.6				Y
16	7.4				1
17	7.4				Y
18	7.4				Y
19	7.6				14
20	9/3	1			
21	7.6				Y
22	8,0				4
23	OFF	-			
24	7.7				Y
25	7.9				N
26	2.8				1
27	7.8				1
28	7.6				1
29	7.7				4
30					,
31					
No = N = Excursion) Total N's					

< <have< th=""><th>Cour</th><th>nty: Columbia</th><th>Agency: REGION 1</th></have<>	Cour	nty: Columbia	Agency: REGION 1
minimums	Е	NTRY	POINT
been met for this day?		EP-	A
	PW	S ID 41	00792
	SCAP	POOSE,	CITY OF
Sample period:		FEBRUAR	4 2024
			nth/Year

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk (Alkalinity)
Print Name: Darry Sykes
Signature: Darry Byles
Date & Phone#: 3/5/2024 503-369-0297
Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

State.