

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

1 2 3 4	8.2				MINEN, SO
3					N
3	8.4				7
1	7.9				1
7			/		-1
5					
6					
7		21			
8					
9	7-8				7
10	7.4				Y
11	7.9				4
12	8.1	18.6			4
13	8.1				4
14	7.4	19			4
15	8.0 7.6				V
16					1
17	7.5				Y
18	7.5				4
19	7.8				У
20	7.8	19			4
21	7.5				Y
22	7.6				Y
23	7.6				4
24	7.7				Y
25	8.4				4
26	8.5				7
27	8.4				Y
28	8.9	18,2			Y
29	8.3	*		,	1
30	8.2	-			4
31	8.2				1

<<Have
minimums
been met for
this day?</pre>

County: Columbia Agency: REGION 1

## **ENTRY POINT**

EP-A

PWS ID 4100792 SCAPPOOSE, CITY OF

Sample period: MAY 2024
Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference	
Minimum Water Quality Parameter(s) as set by State:	
pH 7.2 Alk (Alkalinity)	
Print Name: Darry Sykes	

Signature: 100000 508-369-0297

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/