

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.5				4
1 2	kiron kontrol	Section 1			
3					
4					2 m
5	7.4				4
6	7.4				Y
7	7.4				1
8	7.5	110			1
9	7.4				(
10	7.4	. ( - )			Y
11	7.4				7
12	7.4				1
13	7.4	112			Y
14	7.4			1	V
15	7.4			ļ .	1
16	7.5				/
17	7.4	105			Y
18	7.4				Y
19	7.4				Y
20	7.4				14
21					/
22	7.4				Y
23					
24	7.5				7
25	7.5				1
26	7.21	107			4
27	7.3				7
28	7.21				4
29					
30					
31					
No =	N = Ex	cursio	n) <b>Tot</b> a	al N's	0

< <have minimums<="" th=""><th>County: Columbia Agency: REGION 1  ENTRY POINT</th></have>	County: Columbia Agency: REGION 1  ENTRY POINT
been met for this day?	EP-B
	PWS ID 4100792
	SCAPPOOSE, CITY OF
Sample pe	eriod: APRIL 2022 Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

pH Alk	7.2 90.0	Alkalinit <sub>y</sub>	y)

Date & Phone#: 5/6/2022 503-369-0297
Send to DWP within 10 days after end of

Send to DWP within 10 days after end o sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/