

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

1 2 3 4 5 6 7	7.3 7.2 7.2 7.2 7.2 7.2				7-2-2
	7.3 7.2 7.2 7.2 7.2				4
	7.2 7.2 7.2 7.2				4
	7.2 7.2			parameter in the distribution in the depth of	1 1
	7.2				7
	7,2				4
	-	111			9
	7.5				4
8	7.5				4
9	7.3				4
10	7.9				4
11	7.5				y
12	7.3				4
13	7.3	112			4
14	7.3				4
15	7.3		71	7	Ý
16	7.4				Y
17	7.2				Y
18	7.2				7
19	7.7				7
20	7.2	112			4
21	7.2				Y
22	7.2				4
23	7.2				V
24	7.6				1/
25	7,8				4
26	7.5				9
27	7.3				V
28	7.7	108			7
29	7.6	200			Y
30	7.4				Y
31					

<<Have
minimums
been met for
this day?</pre>

County: Columbia Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100792 SCAPPOOSE, CITY OF

Sample period: June 2022

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference -		
		iter Quality as set by State:
pH Alk	7.2	(Alkalinity)

Signature: Darry Sykes

Date & Phone#: 7/7/2022 503-369-0297

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/