

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	
COLUMN TWO IS NOT	7.3				4
1	74	ps			4
3	7.4				Ч
4	7.5				1/
5	7.3	124			V
6	7.5				4
7	7.5				4
8	7,5	,			Y
9	75				4
10	7.4				4
11	7.3				4
12	7.4				1/
13	7.4	112			4
14	7.4				4
15	1.4				4
16	OFF				
17	7.4		-		4
18 19	7.4		-		Y
20	044		<del> </del>		'
21	A.G				1
22	75				V
23	OFF				7
24	7.4	104			4
25	off	101	-		7
26	off		<b> </b>		
27	7.4	107			1/
28		101			7
29	7.4				Y
30					
31	7.21				4
1 = ok	V = Exc	cursion	) Tota	l N's	(1)

<<Have minimums been met for this day?

County: Columbia Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100792

SCAPPOOSE, CITY OF

Sample period: January 202

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality as set by State
рН	7.2	1
Alk	90.0	(Alkalinity)

Print Name: Darry Sykes

Signature: Davy Dykes

Date & Phone#: 2/6/2023 Eb3-369-0297

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/