

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7,4	lole			4
2 3	OFF				
3	7,5				4
4	OFF				
5	7.5				4
6	OFF			1	
7	7.5	112			7
8	OFF				
9	7.2				4
10	7.4			SOAT BATTE SECURITIES THE PERSONNEL	4
11	OFF				1
12	7.5				4
13	OFF				
14	7.6				4
15	7.le	107			4
16	7.4		1.		4
17	7.7				4
18	1.13				4
19	7,3				4
20	7.身				M
21	7.3				Y
22	7.4	1.10			4
23	7.4	W			Y
24	7.2	-			4
25	7.4				4
26	7.21	110			4
27 28	74	110			4
29	117				7
30			1		
31			:		
			Total		

<<Have minimums been met for this day?

County: Columbia Agency: REGION 1 ENTRY POINT EP-B

PWS ID 4100792 SCAPPOOSE, CITY OF

Sample period: FEBRUARY 2023

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality) as set by State:
pH Alk	7.2 90.0	(Alkalinity)

Print Name: \article article

Signature:

Date & Phone#: 3/9/2023

Send to DWP within 10 days after end of sampling period

(No = N = Excursion) Total N's

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/