## OHA

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рΗ	Alk	Phos	Other	Y/N	<< Have
1						minimums
2						been met for
3						this day?
4						
5	7.4		0.5		Υ	1
6				······································		_
7						
8						1
9						
10						7
11						
12	7.4		0.5		Υ	(Over 9 d
13						Distribut
14						day in w
15						minimun
16						
17						Refere
18						
19	7.4		0.5		Υ	
20						
21						
22						
23						
24						
25					<u></u>	_
26	7.3		0.5		Υ	
27						
28						Print Na
29		ļ				Signatur
30			ļ			_
31						Date & F
(No = N	= Excur	sion)	Т	otal N's	0	

County: Wasco

Agency: REGION 1

## **WICKS ENTRY POINT**

EP-A PWS ID 41-00869 THE DALLES, CITY OF

Sample period: March 2025

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by the State:
pH 7.0
PO4 0.4 (mg/L, Orthophosphate)

Print Name: Tyler Mitchell

Signature:

Date & Phone:

2-Apr-25

541-298-2248 x 5010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp