Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

				-	<u> </u>	
Day	рΗ	Alk	Phos	Other	Y/N	<< Have
1						minimums
2						been met for
3						this day?
4						
5						1
6						1
7	7.1		0.4		Υ	-
8						1
9	•					
10						
11						
12						(Over 9
13						Distribut
14	7.3		0.5		Υ	day in w
15						minimun
16						
17						Refere
18]
19						
20			ļ			
21	7.1		0.5		Υ	
22						
23						
24]
25						
26						
27						
28						Print Na
29	7.0		0.5		Υ	- Signatur
30					<u> </u>	*
31			<u> </u>			Date & F
(No = N	= Excur	rsion)	T	otal N's	0	J

County: Wasco

Agency: REGION 1

WICKS ENTRY POINT

EP-A PWS ID 41-00869 THE DALLES, CITY OF

Sample period: May 2025

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by the State:
pH 7.0
PO4 0.4 (mg/L, Orthophosphate)

Print Name: Tyler Mitchell

Signature:

Date & Phone:

9-Jun-25

541-298-2248 x 5010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp