OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco Agency: REGION 1
1						minimums	Lone Pine Well
2	w					been met for	ENTRY POINT
3	e					this day?	ENTRY POINT
4	1						EP-B
5	1						
6		0.00					PWS ID 41-00869
7	0			565			THE DALLES, CITY OF
8] f f						Sample period: November 2024
9	1						, ,
10	f		1000000			N	umber of excursions during this month:0
11	o					and the state of t	
12	r					(Over 9 ex	cursions in 6 months is a violation. Entry Point and
13						Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.	
14	e						
15	1	100000	1015 (100 to 0				
16	e						
17	C t					Referenc	ce
18	ŀ	16.5				000	National Automorphisms
19	l i	100000					Minimum Water Quality
20	c				200000		Parameter(s) as set by the State:
21	a						
22	1	- 100 (100 (100 (100 (100 (100 (100 (100					pH 7.8
23							204 Control Control
24	r		NOT THE REAL PROPERTY.			4555 1870 1870	PO4 0.4 (Orthophosphate)
25	e				5160 5316		
26	p a	232.3150	- Control of the Cont		50.0	appe a da	
27	i						
28	'r					Print Name: Tyler Mitchell Signature:	
29	s						
30		<u> </u>	<u> </u>	-4-1 611	<u> </u>	Data 9 Bb	ONO! F. Doo 24
(No = N = Excursion) Total N's 0 Date & Phone: 5-Dec-24 541-298-2248 x 5010							

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp