OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alƙ	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1	8.1		0.6		Υ	minimums	Lone P	ine Well
2						been met for		
3			:			this day?	ENIK	Y POINT
4	8.1		0.6		Υ			P-B
5	8.0		0.5		Υ		_	
6							PWS ID	41-00869
7							THE DALI	LES, CITY OF
8							Sample period: Septem	ber 2025
9						_	Sample period. Septem	DCI 2025
10						N	umber of excursions during	g this month: 0
11	8.0		0.5		Y			
12	8.0		0.6		Y	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
13								
14								
15	8.1		0.5		Υ			
16								
17						Referenc	ce	
18								-
19	8.1		0.5		Υ	_	Minimum Water Qua	ality
20							Parameter(s) as set l	by the State:
21						_		
22							pH 7.8	
23	8.1		0.5		Υ	.		
24			<u> </u>		<u> </u>	.	PO4 0.4 (Orthop	hosphate)
25						4		
26							······	
27			ļ					
28						Print Nam	e: Tyler Mitchell	Ā
29						Signature:	Tulling	/ /
30						J.B	7	
(No = N	= Excur	sion)	T	otal N's	0	Date & Ph	one: 8-Oct-25	541-298-2248 x 5010

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp