OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1	
1						minimums	Jord	lan Well	
2						been met for			
3						this day?	ENT	RY POINT	
4								EP-C	
5							::- 		
6	8.2		0.5		Υ		PWS II	O 41-00869	
7	8.4		0.5		Υ		THE DAI	LES, CITY OF	
8						-	Sample period: June 2	023	
9						4			
10						N	umber of excursions duri	ng this month:0	
11					7000	4			
12	8.6		0.6	ļ	Υ	(Over 9 excursions in 6 months is a violation. Entry Point and			
13					-		n excursions are cumulati		
14						day in which the water quality parameter(s) fall below the minimum set by the State.			
15	_				-				
16						-			
17			-			Reference	re		
18 19	-					-	Minimum Water Qu	ıality	
20	-				<u> </u>	1	Parameter(s) as set	()	
21	8.4		0.4		Υ	1	Parameter(s) as set	by the State:	
22	0.4		0.4		<u> </u>	1	pH 7.8		
23						1			
24						1	PO4 0.4 (Ortho	phosphate)	
25						7	, and a second		
26	8.6		0.5		Υ	1			
27									
28						Print Name	e: Larry McCollum	^	
29	8.4		0.5		Υ	Cignoturo			
30	8.4		0.5		Υ	Signature:			

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp