Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other	Y/N	<< Have
1				OFF		minimums
2				OFF		been met for
3				OFF		this day?
4				OFF		
5				OFF		
6				OFF		
7				OFF		
8				OFF		
9				OFF		
10				OFF		
11				OFF]
12				OFF		(Over 9 e
13				OFF		Distributi
14				OFF		day in w
15				OFF		minimum
16				OFF		
17				OFF		Referen
18	8.0		0.5		Υ	
19						
20						
21	8.2		0.4		Υ]
22	8.2		0.5		Υ	
23	8.0		0.5		Υ]
24	8.2		0.5		Υ]
25]
26	8.1		0.5		Υ	
27	8.1		0.4		Υ	
28	8.1		0.4		Υ	Print Nan
29	8.1		0.5		Υ	Signature
30						Signature
(No = N = Excursion)			Total N's		0	Date & Ph

County: Wasco	Agency: REGION 1
---------------	------------------

Marks Well **ENTRY POINT**

EP-D PWS ID 41-00869 THE DALLES, CITY OF

Sample period: June 2021

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

F	Reference
	Minimum Water Quality Parameter(s) as set by the State:
	pH 7.6
	PO4 0.4 (Orthophosphate)

Print Name: Larry McCollum

Signature:

Date & Phone: 09 Aul 2021; 541-298-2248 x 5000

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp