## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

				-	ОР		1		0.
Day	рН	Alk	Phos	Other	Y/N	<< Have	County: W	'asco	Agency: REGION 1
1		OFF FC	OR THE S	SEASON		minimums	Marks Well		
2	OFF FOR THE SEASON					been met for	ENTRY POINT		
3	OFF FOR THE SEASON					this day?	ENTRYPOINT		
4	OFF FOR THE SEASON							F	P-D
5	OFF FOR THE SEASON					_	_		_
6	OFF FOR THE SEASON					PWS ID 41-00869			
7	OFF FOR THE SEASON					THE DALLES, CITY OF			
8	OFF FOR THE SEASON					Sample period: May 2024			
9	OFF FOR THE SEASON								
10	8.0		0.6		Y	N	umber of excursio	ns during	this month: 0
11									
12						(Over 9 exc	cursions in 6 mont	hs is a vic	lation. Entry Point and
13	8.1		0.7		Υ	Distribution excursions are cumulative). An 'excursion' is any			
14						7	•	lity parar	neter(s) fall below the
15						minimum s	et by the State.		
16									
17						Referenc	re		
18									10.
19						-	Minimum Wa	•	•
20						4 1	Parameter(s)	as set b	y the State:
21	8.0		0.6		Y	4 1			
22						-	pH 7.6		
23						4			
24	8.0		0.5		Y	4	PO4 0.4	(Orthoph	ospnate)
25						-			
26					-				
27						<b>-</b>			
28						Print Name	: Larry McCollum	$\gamma \cap \cap$	
29						Signature:	THE	20	and the state of t
30						Date & Pho	one: 66June	24	541-298-2248 x 5010
(NIS NI	<u> </u>	-:	<u> </u>	atal NII-		J Date & Pilo	Jule. O 6 June	-24	241-739-7749 X 2010
(No = N	= Excur	sion)		otal N's	0	J			

Well inspected daily. Samples collected when

well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp