OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1						minimums	Marks Well	
2						been met for		Y POINT
3			100			this day?	ENIR	T POINT
4							F	P-D
5								
6	l W							41-00869
7	e I i						THE DAL	LES, CITY OF
8 9	i						Sample period: Decem	ber 2024
10						N	umber of excursions durin	ig this month: 0
11	o f							***************************************
12] ;		-			(Over 9 exc	cursions in 6 months is a v	violation. Entry Point and
13						Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
14	f							
15	o							
16	r							
17						Referenc	ie	
18	t .		100					
19	h						Minimum Water Qu	ıality
20	_ e						Parameter(s) as set	by the State:
21	- 5							
22	e						pH 7.6	
23	a							
24	s						PO4 0.4 (Orthor	phosphate)
25	0							
26	n							,
27								
28						Print Name: Tyler Mitchell Signature: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
29			18.00					
30								
31								
(No = N = Excursion) Total N's 0 Date & Phone: 9-Jan-25 541-298-2248 x 5010								

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp