OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1	W					minimums	Marks Well	
2	e					been met for	ENTRY POINT	
3	1					this day?	ENII	RY POINT
4							1	EP-D
5	o							
6	f					PWS ID 41-00869		
7	f					THE DALLES, CITY OF		
8	d					_	Sample period: June 2	.025
9	u					, · ·		
10	е				<u> </u>	Number of excursions during this month: 0		
11	t					4		
12	ò					(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
13								
14	m				ļ			
15	е			· · · · · · · · · · · · · · · · · · ·				
16	C h				·	1 5		···
17	a					Referenc	ce	
18	n						Minimum Water Q	uality
19 20	j					1	Parameter(s) as set	· · · · · · · · · · · · · · · · · · ·
21	c a			<u> </u>		-	rarameter(s) as set	. by the State:
22	1 1					1	pH 7.6	
23						1	F.,	
24	f a					-	PO4 0.4 (Ortho	phosphate)
25	i							,
26	1		<u> </u>					
27	u				<u> </u>		***************************************	
28	1					Print Name	e: Tyler Mitchell	4 4
29	е					1 All		
30						- Signature:	ty ~ Cu	
(No = N = Excursion) Total N's 0 Date & Phone: 7/10/2025 541-298-2248 x 5010								

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp