



Water Quality Parameter Monitoring Form

**Lead & Copper Rule Corrosion Control**

County: Tillamook

Agency: Region 1

**ENTRY POINT**

**EP- C**

Day	pH	Alk	Phos	Sili	Y/N	<< Have
1					OFF	minimums
2	7.46	63			Y	been met
3	8.65				Y	for this day?
4					OFF	
5					OFF	
6					OFF	
7					OFF	
8					OFF	
9	7.47	64			Y	
10					OFF	
11					OFF	
12					OFF	
13					OFF	
14					OFF	
15					OFF	
16					OFF	
17					OFF	
18					OFF	
19	7.66	64			Y	
20					OFF	
21					OFF	
22					OFF	
23	7.42	64			Y	
24					OFF	
25					OFF	
26					OFF	
27					OFF	
28					OFF	
29						
30						
31						

PWS ID: 41

**System Name:** Tillamook Water Dept, City of

**Sample Period** February, 2026  
Month/Year

**Number of excursions\* during this month:** 0  
( Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are Cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State

**Minimum Water Quality Parameters as set by State:**

pH   
Alk  (Alkalinity)

**Print Name:** Austin Harmon

**Signature:**

**Date:** March 10, 2026

=N=Excursion) **Total N's**

Send to DHS within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>